

Certificate of Analysis - Fax Copy

MASI ENVIRONMENTAL SERVICES

P. O. Box 1440
 Dublin, Ohio 43017
 (614) 873-4654

Page: 1
 Date: 09/10/18

WHITEHOUSE VILLAGE OF
 STEVE PILCHER
 PO BOX 2476

 WHITEHOUSE OH 43571-0000

Client No: 0000000606
 AR Sheet No: 0621822-AR
 MASI Dublin Laboratory: 877
 MASI Cincinnati Laboratory: 4100
 PWS ID No: 4801612
 STU ID No: DS1
 PO No:

Dear Client:

Along with your results listed below we would like to thank you for allowing MASI to assist you with your environmental testing requirements.

Account Name: WHITEHOUSE VILLAGE OF Public
 Sampler Name: AUSTIN MYERS County: LUCAS
 Sample Date: 08/13/18 Chlorinated:
 Sample Time: 10:25 Repeat No:
 Sample Matrix: POTABLE C12 Total:
 Sample Monitoring Point: DS000 C12 Free:
 Sample Tap: HYDRANT C12 Combined:
 Sample Type:
 Sample Address: 6317 FINZEL RD WHITEHOUSE SPECIAL
 Sample ID:

Test Requested	Lab Number	Method Number	Analyst Number	Date Analyzed
Trihalomethane LISTED BELOW ug/l	87918	524.2	2597	08/17/18
CHLOROFORM 40.4 ug/l	87466	524.2	2597	08/17/18
BROMOFORM 1.7 ug/l	87467	524.2	2597	08/17/18
BROMODICHLOROMETHANE 15.6 ug/l	87468	524.2	2597	08/17/18
DIBROMOCHLOROMETHANE 8.7 ug/l	87469	524.2	2597	08/17/18
TTHM 66.4 ug/l	87470	524.2	2597	08/17/18

Certificate of Analysis - Fax Copy

MASI ENVIRONMENTAL SERVICES

P. O. Box 1440
 Dublin, Ohio 43017
 (614) 873-4654

Page: 1
 Date: 09/10/18

WHITEHOUSE VILLAGE OF
 STEVE PILCHER
 PO BOX 2476

 WHITEHOUSE OH 43571-0000

Client No: 0000000606
 AR Sheet No: 0621823-AR
 MASI Dublin Laboratory: 877
 MASI Cincinnati Laboratory: 4100
 PWS ID No: 4801612
 STU ID No: DS1
 PO No:

Dear Client:

Along with your results listed below we would like to thank you for allowing MASI to assist you with your environmental testing requirements.

Account Name: WHITEHOUSE VILLAGE OF	Public
Sampler Name: AUSTIN MYERS	County: LUCAS
Sample Date: 08/13/18	Chlorinated:
Sample Time: 10:11	Repeat No:
Sample Matrix: POTABLE	C12 Total:
Sample Monitoring Point: DS000	C12 Free:
Sample Tap: SINK	C12 Combined:
Sample Type:	
Sample Address: 6010 N TEXAS ST WHITEHOUSE SPECIAL	
Sample ID:	

Test Requested	Lab Number	Method Number	Analyst Number	Date Analyzed
Trihalomethane LISTED BELOW ug/l	87910	524.2	2597	08/16/18
Haloacetic acid 5 LISTED BELOW ug/l	87911	EPA 552.3	8	09/06/18
CHLOROFORM 32.4 ug/l	87407	524.2	2597	08/16/18
BROMOFORM 1.7 ug/l	87408	524.2	2597	08/16/18
BROMODICHLOROMETHANE 13.8 ug/l	87409	524.2	2597	08/16/18
DIBROMOCHLOROMETHANE 8.1 ug/l	87410	524.2	2597	08/16/18
TTHM 56.0 ug/l	87411	524.2	2597	08/16/18

Certificate of Analysis - Fax Copy

MASI ENVIRONMENTAL SERVICES

P. O. Box 1440
 Dublin, Ohio 43017
 (614) 873-4654

Page: 2
 Date: 09/10/18

WHITEHOUSE VILLAGE OF
 STEVE PILCHER
 PO BOX 2476

 WHITEHOUSE OH 43571-0000

Client No: 0000000606
 AR Sheet No: 0621823-AR
 MASI Dublin Laboratory: 877
 MASI Cincinnati Laboratory: 4100
 PWS ID No: 4801612
 STU ID No: DS1
 PO No:

Dear Client:

Along with your results listed below we would like to thank you for allowing MASI to assist you with your environmental testing requirements.

Account Name: WHITEHOUSE VILLAGE OF Public
 Sampler Name: AUSTIN MYERS County: LUCAS
 Sample Date: 08/13/18 Chlorinated:
 Sample Time: 10:11 Repeat No:
 Sample Matrix: POTABLE C12 Total:
 Sample Monitoring Point: DS000 C12 Free:
 Sample Tap: SINK C12 Combined:
 Sample Type:
 Sample Address: 6010 N TEXAS ST WHITEHOUSE SPECIAL
 Sample ID:

Test Requested	Lab Number	Method Number	Analyst Number	Date Analyzed
MONOCHLOROACETIC ACID <2.0 ug/l	87412	552.3	8	09/06/18
DICHLOROACETIC ACID 9.6 ug/l	87413	552.3	8	09/06/18
TRICHLOROACETIC ACID <1.0 ug/l	87414	552.3	8	09/06/18
MONOBROMOACETIC ACID <1.0 ug/l	87415	552.3	8	09/06/18
DIBROMOACETIC ACID 3.3 ug/l	87416	552.3	8	09/06/18
TOTAL HALOACETIC ACIDS (HAA5) 12.9 ug/l	87417	552.3	8	09/06/18

Certificate of Analysis - Fax Copy

MASI ENVIRONMENTAL SERVICES

P. O. Box 1440
 Dublin, Ohio 43017
 (614) 873-4654

Page: 1
 Date: 09/10/18

WHITEHOUSE VILLAGE OF
 STEVE PILCHER
 PO BOX 2476

 WHITEHOUSE OH 43571-0000

Client No: 0000000606
 AR Sheet No: 0621824-AR
 MASI Dublin Laboratory: 877
 MASI Cincinnati Laboratory: 4100
 PWS ID No: 4801612
 STU ID No: DS1
 PO No:

Dear Client:

Along with your results listed below we would like to thank you for allowing MASI to assist you with your environmental testing requirements.

Account Name: WHITEHOUSE VILLAGE OF Public
 Sampler Name: AUSTIN MYERS County: LUCAS
 Sample Date: 08/13/18 Chlorinated:
 Sample Time: 09:55 Repeat No:
 Sample Matrix: POTABLE C12 Total:
 Sample Monitoring Point: DS000 C12 Free:
 Sample Tap: HOSE BIB C12 Combined:
 Sample Type:
 Sample Address: 6763 GILEAD ST WHITEHOUSE SPECIAL
 Sample ID:

Test Requested	Lab Number	Method Number	Analyst Number	Date Analyzed
Trihalomethane LISTED BELOW ug/l	87916	524.2	2597	08/17/18
CHLOROFORM 48.1 ug/l	87451	524.2	2597	08/17/18
BROMOFORM 1.7 ug/l	87452	524.2	2597	08/17/18
BROMODICHLOROMETHANE 16.2 ug/l	87453	524.2	2597	08/17/18
DIBROMOCHLOROMETHANE 9.0 ug/l	87454	524.2	2597	08/17/18
TTHM 74.9 ug/l	87455	524.2	2597	08/17/18

Certificate of Analysis - Fax Copy

MASI ENVIRONMENTAL SERVICES

P. O. Box 1440
 Dublin, Ohio 43017
 (614) 873-4654

Page: 1
 Date: 09/10/18

WHITEHOUSE VILLAGE OF
 STEVE PILCHER
 PO BOX 2476

 WHITEHOUSE OH 43571-0000

Client No: 0000000606
 AR Sheet No: 0621825-AR
 MASI Dublin Laboratory: 877
 MASI Cincinnati Laboratory: 4100
 PWS ID No: 4801612
 STU ID No: DS1
 PO No:

Dear Client:

Along with your results listed below we would like to thank you for allowing MASI to assist you with your environmental testing requirements.

Account Name: WHITEHOUSE VILLAGE OF Public
 Sampler Name: AUSTIN MYERS County: LUCAS
 Sample Date: 08/13/18 Chlorinated:
 Sample Time: 09:29 Repeat No:
 Sample Matrix: POTABLE C12 Total:
 Sample Monitoring Point: DS202 C12 Free:
 Sample Tap: HYDRANT C12 Combined:
 Sample Type:
 Sample Address: 7344 PROVIDENCE ST WHITEHOUSE
 Sample ID:

Test Requested	Lab Number	Method Number	Analyst Number	Date Analyzed
Trihalomethane LISTED BELOW ug/l	87914	524.2	2597	08/16/18
Haloacetic acid 5 LISTED BELOW ug/l	87915	EPA 552.3	8	09/06/18
CHLOROFORM 55.7 ug/l	87436	524.2	2597	08/16/18
BROMOFORM 1.8 ug/l	87437	524.2	2597	08/16/18
BROMODICHLOROMETHANE 16.7 ug/l	87438	524.2	2597	08/16/18
DIBROMOCHLOROMETHANE 9.1 ug/l	87439	524.2	2597	08/16/18
TTHM 83.3 ug/l	87440	524.2	2597	08/16/18

Certificate of Analysis - Fax Copy

MASI ENVIRONMENTAL SERVICES

P. O. Box 1440
 Dublin, Ohio 43017
 (614) 873-4654

Page: 2
 Date: 09/10/18

WHITEHOUSE VILLAGE OF
 STEVE PILCHER
 PO BOX 2476

 WHITEHOUSE OH 43571-0000

Client No: 0000000606
 AR Sheet No: 0621825-AR
 MASI Dublin Laboratory: 877
 MASI Cincinnati Laboratory: 4100
 PWS ID No: 4801612
 STU ID No: DS1
 PO No:

Dear Client:

Along with your results listed below we would like to thank you for allowing MASI to assist you with your environmental testing requirements.

Account Name: WHITEHOUSE VILLAGE OF Public
 Sampler Name: AUSTIN MYERS County: LUCAS
 Sample Date: 08/13/18 Chlorinated:
 Sample Time: 09:29 Repeat No:
 Sample Matrix: POTABLE C12 Total:
 Sample Monitoring Point: DS202 C12 Free:
 Sample Tap: HYDRANT C12 Combined:
 Sample Type:
 Sample Address: 7344 PROVIDENCE ST WHITEHOUSE
 Sample ID:

Test Requested	Lab Number	Method Number	Analyst Number	Date Analyzed
MONOCHLOROACETIC ACID <2.0 ug/l	87441	552.3	8	09/06/18
DICHLOROACETIC ACID 13.6 ug/l	87442	552.3	8	09/06/18
TRICHLOROACETIC ACID <1.0 ug/l	87443	552.3	8	09/06/18
MONOBROMOACETIC ACID <1.0 ug/l	87444	552.3	8	09/06/18
DIBROMOACETIC ACID 3.0 ug/l	87445	552.3	8	09/06/18
TOTAL HALOACETIC ACIDS (HAA5) 16.7 ug/l	87446	552.3	8	09/06/18

Certificate of Analysis - Fax Copy

MASI ENVIRONMENTAL SERVICES

P. O. Box 1440
 Dublin, Ohio 43017
 (614) 873-4654

Page: 1
 Date: 09/10/18

WHITEHOUSE VILLAGE OF
 STEVE PILCHER
 PO BOX 2476

 WHITEHOUSE OH 43571-0000

Client No: 0000000606
 AR Sheet No: 0621827-AR
 MASI Dublin Laboratory: 877
 MASI Cincinnati Laboratory: 4100
 PWS ID No: 4801612
 STU ID No: DS1
 PO No:

Dear Client:

Along with your results listed below we would like to thank you for allowing MASI to assist you with your environmental testing requirements.

Account Name: WHITEHOUSE VILLAGE OF Public
 Sampler Name: AUSTIN MYERS County: LUCAS
 Sample Date: 08/13/18 Chlorinated:
 Sample Time: 09:07 Repeat No:
 Sample Matrix: POTABLE C12 Total:
 Sample Monitoring Point: DS000 C12 Free:
 Sample Tap: HOSE BIB C12 Combined:
 Sample Type:
 Sample Address: 8770 DUTCH RD WHITEHOUSE SPECIAL
 Sample ID:

Test Requested	Lab Number	Method Number	Analyst Number	Date Analyzed
Trihalomethane LISTED BELOW ug/l	87917	524.2	2597	08/17/18
CHLOROFORM 37.2 ug/l	87459	524.2	2597	08/17/18
BROMOFORM 1.9 ug/l	87460	524.2	2597	08/17/18
BROMODICHLOROMETHANE 15.8 ug/l	87461	524.2	2597	08/17/18
DIBROMOCHLOROMETHANE 9.0 ug/l	87462	524.2	2597	08/17/18
TTHM 63.9 ug/l	87463	524.2	2597	08/17/18

Certificate of Analysis - Fax Copy

MASI ENVIRONMENTAL SERVICES

P. O. Box 1440
 Dublin, Ohio 43017
 (614) 873-4654

Page: 1
 Date: 09/10/18

WHITEHOUSE VILLAGE OF
 STEVE PILCHER
 PO BOX 2476

 WHITEHOUSE OH 43571-0000

Client No: 0000000606
 AR Sheet No: 0621828-AR
 MASI Dublin Laboratory: 877
 MASI Cincinnati Laboratory: 4100
 PWS ID No: 4801612
 STU ID No: DS1
 PO No:

Dear Client:

Along with your results listed below we would like to thank you for allowing MASI to assist you with your environmental testing requirements.

Account Name: WHITEHOUSE VILLAGE OF Public
 Sampler Name: AUSTIN MYERS County: LUCAS
 Sample Date: 08/13/18 Chlorinated:
 Sample Time: 11:05 Repeat No:
 Sample Matrix: POTABLE C12 Total:
 Sample Monitoring Point: DS201 C12 Free:
 Sample Tap: HYDRANT C12 Combined:
 Sample Type:
 Sample Address: 7125 BERKEY SOUTHERN WHITEHOUSE
 Sample ID:

Test Requested	Lab Number	Method Number	Analyst Number	Date Analyzed
Trihalomethane LISTED BELOW ug/l	87912	524.2	2597	08/16/18
Haloacetic acid 5 LISTED BELOW ug/l	87913	EPA 552.3	8	09/06/18
CHLOROFORM 58.3 ug/l	87420	524.2	2597	08/16/18
BROMOFORM 1.8 ug/l	87421	524.2	2597	08/16/18
BROMODICHLOROMETHANE 17.6 ug/l	87422	524.2	2597	08/16/18
DIBROMOCHLOROMETHANE 9.4 ug/l	87423	524.2	2597	08/16/18
TTHM 87.2 ug/l	87424	524.2	2597	08/16/18

Certificate of Analysis - Fax Copy

MASI ENVIRONMENTAL SERVICES

P. O. Box 1440
 Dublin, Ohio 43017
 (614) 873-4654

Page: 2
 Date: 09/10/18

WHITEHOUSE VILLAGE OF
 STEVE PILCHER
 PO BOX 2476

 WHITEHOUSE OH 43571-0000

Client No: 0000000606
 AR Sheet No: 0621828-AR
 MASI Dublin Laboratory: 877
 MASI Cincinnati Laboratory: 4100
 PWS ID No: 4801612
 STU ID No: DS1
 PO No:

Dear Client:

Along with your results listed below we would like to thank you for allowing MASI to assist you with your environmental testing requirements.

Account Name: WHITEHOUSE VILLAGE OF Public
 Sampler Name: AUSTIN MYERS County: LUCAS
 Sample Date: 08/13/18 Chlorinated:
 Sample Time: 11:05 Repeat No:
 Sample Matrix: POTABLE C12 Total:
 Sample Monitoring Point: DS201 C12 Free:
 Sample Tap: HYDRANT C12 Combined:
 Sample Type:
 Sample Address: 7125 BERKEY SOUTHERN WHITEHOUSE
 Sample ID:

Test Requested	Lab Number	Method Number	Analyst Number	Date Analyzed
MONOCHLOROACETIC ACID <2.0 ug/l	87425	552.3	8	09/06/18
DICHLOROACETIC ACID 12.6 ug/l	87426	552.3	8	09/06/18
TRICHLOROACETIC ACID <1.0 ug/l	87427	552.3	8	09/06/18
MONOBROMOACETIC ACID <1.0 ug/l	87428	552.3	8	09/06/18
DIBROMOACETIC ACID 2.8 ug/l	87429	552.3	8	09/06/18
TOTAL HALOACETIC ACIDS (HAA5) 15.4 ug/l	87430	552.3	8	09/06/18